HOWARD CHEVROLET

Mr. Marvin Howard, President Howard's Chevrolet, Company, Inc. 515 South Walnut Street Bloomington, Indiana

Dear Mr. Howard:

Enclosed is the latest Plot Plan of your site. I believe the locations to be correct.

I want you to note the difference in grades between Mr. Stapleton and Mr. Strain's topo. I called Mr. Stapleton this mouning, Monday, August 26, and found out he assumed an elevation of 500 from, I believe, a fire hydrant. He mentioned that Mr. Strain took his topo from a government topo print. These prints generally vary both horizontilly and vertically.

I would like to suggest we have Mr. Stapleton take this Plot Plan and tie down these elevations. At the same time, I would like to have center line grades every 100° in front of the property. I will also shown the general location of the septic system leaching field and if satisfactory with you, Mr. Stapleton should make a percolation test for the Health Department.

Thanking you for your continued cooperation.

Cordially,

PACKAGED BUILDINGS, INC.


W. M. Loxley, P.E.

WML: plp

encls.

cc. Mr. J. J. Dues
Mr. John Stapleton

FILE UNDER



PRELIMINARY PLOT PLAN

SCALE 1"= 30-0"

HOWARDS CHEVROLET

8 LOOMINGTUN IND.

PACKAGED BLDG'S INC.

DHYTON, UH FO.

